

# Oil Field Environmental Incident Summary

**Incident:** 20131219155258      **Date/Time of Notice:** 12/18/2013 12:00

**Responsible Party:** NEWFIELD PRODUCTION COMPANY

**Well Operator:** NEWFIELD PRODUCTION COMPANY

**Well Name:** CHAMELEON STATE 153-97-16-21-2H

**Field Name:** BANKS

**Well File #:** 22621

**Date Incident:** 12/18/2013      **Time Incident:** 10:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 153

**Rng:** 97

**Sec:** 16

**Qtr:** NW NE

**Location Description:**

**Submitted By:** William (Buzz) Redfield

**Received By:**

**Contact Person:** KUMEKO DOYLE  
363 N. SAM HOUSTON, PKWY E  
SUITE 100  
HOUSTON, TX 77060

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

|       | Spilled | Units   | Recovered | Units   | Followup | Units   |
|-------|---------|---------|-----------|---------|----------|---------|
| Oil   | 0       | barrels | 0         | barrels |          |         |
| Brine | 140     | barrels | 140       | barrels | 140      | barrels |
| Other | 0       | barrels | 0         | barrels |          |         |

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 10/14/2014      **Clean Up Concluded:** 1/2/2014

**Risk Evaluation:**

**Areal Extent:**

***Potential Environmental Impacts:***

***Action Taken or Planned:***

Vacuum truck was called out and sucked up all of the salt water. The ground was frozen, so was an easy clean-up.

***Wastes Disposal Location:*** The salt-water was hauled to a salt-water disposal.

***Agencies Involved:***

***Updates***

---

***Date:*** 12/19/2013 ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Roberts, Kris

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release, due to unspecified cause, remained on location within the diking, according to the report. NDIC retains oversight.